

HEALTH & WELFARE

DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@dhw.idaho.gov

May 3, 2010

Steve Silberberger, Administrator Seven Oaks Community Homes-- Knapp West 3940 West 5th Avenue #C Post Falls, Idaho 83854

RE: Seven Oaks Community Homes-- Knapp West, Provider #13G068

Dear Mr. Silberberger:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Seven Oaks Community Homes-- Knapp West, on April 19, 2010.

Enclosed is your copy of a Statement of Deficiencies/Plan of Correction, form CMS-2567, which states that no Medicaid deficiencies were noted at the time of the survey. Also, enclosed is a similar form stating that no State licensure deficiencies were noted at the time of the survey.

Thank you for the courtesies extended to us during our visit. If we can be of any help to you, please call our office at (208) 334-6626.

Sincerely,

TOM MROZ

Health Facility Surveyor

Facility Fire Safety and Construction Program

TM/li

Enclosure

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 04/26/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 03			(X3) DATE SURVEY COMPLETED	
		13G068	13G068		B. WING		04/19/2010	
NAME OF PROVIDER OR SUPPLIER SEVEN OAKS COMMUNITY HOMES - KNAPP \ 2898 KNAPP CIRCLE POST FALLS, ID 83854								
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K 000	K 000 INITIAL COMMENTS			K 000			0.000	
LABORATO	INITIAL COMMENTS Surveyor: 27570 The facility is a single story, 1,500 s.f. residential structure of Type V(000) construction. The building consists of three (3) bedrooms, two (2) full bathrooms, a common living/dining/kitchen area, laundry, and a two (2) car attached garage. Fire/life safety features include a complete fire alarm/smoke detection system with detection in the common areas and each sleeping room; a modified sprinkler system designed/installed per NFPA Std 13d with coverage provided in all habitable spaces and closets. The facility was found to be in substantial compliance with applicable fire/life safety requirements during the annual fire/life safety survey conducted on April 19, 2010. The facility was surveyed under the Life Safety Code, 2000 Edition, Chapter 32, New Residential Board & Care Occupancies, Impractical Evacuation Capability in accordance with 42 CFR 483.470 (j). The survey was conducted by: Tom Mroz CFI-II Health Facility Surveyor Fire/Life Safety and Construction			RNATI IDE	TITLE		(X6) DATE	

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

PRINTED: 04/26/2010 FORM APPROVED

Bureau of Facility Standards STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 03 B. WING 04/19/2010 13G068 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE SEVEN OAKS COMMUNITY HOMES - KNAPP WES 2898 KNAPP CIRCLE POST FALLS, ID 83854 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DATE DEFICIENCY) M 000 16.03.11 Inital Comments M 000 Surveyor: 27570 The facility is a single story, 1,500 s.f. residential structure of Type V(000) construction. The building consists of three (3) bedrooms, two (2) full bathrooms, a common living/dining/kitchen area, laundry, and a two (2) car attached garage. Fire/life safety features include a complete fire alarm/smoke detection system with detection in the common areas and each sleeping room; a modified sprinkler system designed/installed per NFPA Std 13d with coverage provided in all habitable spaces and closets. The facility was found to be in substantial compliance with applicable fire/life safety requirements during the annual Fire/Life Safety survey conducted on April 19, 2010. The facility was surveyed under the LIFE SAFETY CODE, 1976 Edition, Residential Board & Care Occupancies, Impractical Evacuation Capability in accordance with IDAPA 16.03.11 The Survey was conducted by: Tom Mroz CFI-II Health Facility Surveyor Fire/Life Safety and Construction

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

4QRL21

(X6) DATE